

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	34	219/130.01.ccls.	US-PGPU B	OR	ON	2007/04/25 17:03
L2	56	219/130.1.ccls.	US-PGPU B	OR	ON	2007/04/25 17:04
L3	60	219/130.5.ccls.	US-PGPU B	OR	ON	2007/04/25 17:05
L4	18	219/130.4.ccls.	US-PGPU B	OR	ON	2007/04/25 17:05
L5	60	219/130.21.ccls.	US-PGPU B	OR	ON	2007/04/25 17:05
L6	2	219/130.31.ccls.	US-PGPU B	OR	ON	2007/04/25 17:05
L7	4	219/130.32.ccls.	US-PGPU B	OR	ON	2007/04/25 17:05
L8	14	219/130.33.ccls.	US-PGPU B	OR	ON	2007/04/25 17:05
L9	58	219/130.51.ccls.	US-PGPU B	OR	ON	2007/04/25 17:05
L10	21	219/132.ccls.	US-PGPU B	OR	ON	2007/04/25 17:06
L11	37	219/137PS.ccls.	US-PGPU B	OR	ON	2007/04/25 17:06

INTERFERENCE SEARCH

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L12	1	((weld\$3 same ((set\$4 or adjust\$3 or updat\$3 or chang\$3) same parameter) same signal same ((external or remote or exterior) same operat\$3 same unit))and (control\$5 same evaluat\$3)).clm.	US-PGPU B	OR	ON	2007/04/25 17:21
L14	0	((weld\$3 same ((set\$4 or adjust\$3 or updat\$3 or chang\$3) same (Plurality same parameter)) same (signal or sensor or sens\$3) same ((external or remote or exterior) same operat\$3 same unit))and (control\$5 same evaluat\$3)).clm.	US-PGPU B	OR	ON	2007/04/25 17:20
L15	0	((weld\$3 same ((set\$4 or adjust\$3 or updat\$3 or chang\$3) same (Plurality and parameter)) same (signal or sensor or sens\$3) same ((external or remote or exterior) same operat\$3 same unit))and (control\$5 same evaluat\$3)).clm.	US-PGPU B	OR	ON	2007/04/25 17:18
L16	0	((weld\$3 same ((set\$4 or adjust\$3 or updat\$3 or chang\$3) and (Plurality same parameter)) same (signal or sensor or sens\$3) same ((external or remote or exterior) same operat\$3 same unit))and (control\$5 same evaluat\$3)).clm.	US-PGPU B	OR	ON	2007/04/25 17:18

EAST Search History

L17	1	((weld\$3 same ((set\$4 or adjust\$3 or updat\$3 or chang\$3) same parameter) same (signal or sensor or sens\$3) same ((external or remote or exterior) same operat\$3 same unit))and (control\$5 same evaluat\$3)).clm.	US-PGPU B	OR	ON	2007/04/25 17:19
L18	5	((weld\$3 and ((set\$4 or adjust\$3 or updat\$3 or chang\$3) same parameter) and (signal or sensor or sens\$3) and ((external or remote or exterior) same operat\$3 same unit))and (control\$5 same evaluat\$3)).clm.	US-PGPU B	OR	ON	2007/04/25 17:19
L19	0	((weld\$3 same ((set\$4 or adjust\$3 or updat\$3 or chang\$3) same (Plurality same parameter)) same ((external or remote or exterior) same operat\$3 same unit))and (control\$5 same evaluat\$3)).clm.	US-PGPU B	OR	ON	2007/04/25 17:20
L20	1	((weld\$3 same ((set\$4 or adjust\$3 or updat\$3 or chang\$3) same parameter) same ((external or remote or exterior) same operat\$3 same unit))and (control\$5 same evaluat\$3)).clm.	US-PGPU B	OR	ON	2007/04/25 17:21
L21	1	((weld\$3 same ((set\$4 or adjust\$3 or updat\$3 or chang\$3) same parameter) same (external or remote or exterior)) and (control\$5 same evaluat\$3)).clm.	US-PGPU B	OR	ON	2007/04/25 17:22